

ADAPTIVE DYNAMICS

See **51, GENERAL WARNING/INFORMATION MESSAGE (AMBER)**. If this warning lamp illuminates and the message **ADAPTIVE DYNAMICS FAULT** is displayed in the Message centre, some reduction in ride comfort may be experienced. Also see **51, WARNING LAMPS AND INDICATORS**. If the fault persists, consult a Dealer/Authorised Repairer.