

ADAPTIVE DYNAMICS

If the general warning lamp illuminates (see **44, GENERAL WARNING/INFORMATION MESSAGE (AMBER)**) and the message **ADAPTIVE DYNAMICS FAULT** is displayed in the Message centre, some reduction in ride comfort may be experienced. If the fault persists, consult a Retailer/Authorised Repairer.